


APPENDIX 3

Bromley - Tweedy Road
Development Report
HolderMathiasarchitects



Previous planning application and inspectors report

Comments from the inspectors report

Overdevelopment of the site

elevation was raised as was the hard relationship landscaping to ease the interstitial space scheme offered little opportunity for effective with the pavement. It was remarked that the excessive in bulk and size. The lack of relief in The inspector believed that the 72 unit scheme was

N Harmful to the adjacent conservation area and listed buildings

The relationship of the proposed building and the grade II listed building perpendicular to the site was poorly considered. In particular there were proposed development and Sheppards College concerns regarding overlooking between the Views from the north from tweedy road were also

CGI provided by Proctor Matthews Architects

Harmful to the amenities of the occupiers of Bromley and Sheppards Coleges

ω

The inspector did not believe that the scale of the building had too detrimental effect on the amenity of the adjacent listed buildings.

Poor quality amenity space

854.5

buildings and tress surrounding it. The shared garden was seen to be long, narrow and hemmed in which would provide restricted daylight due to its location and the mass of the

Appearance and Character


no views through the site towards the conservation appearence of the scheme. The design also offered was unconvinced by the 'out of character' area which was seen as a dissapointment Further to the issues of bulk and size the inspector

Parking provision

The inspector believed that the parking provided was sufficient for such a site. The scheme provided parking for 47% of units.


Site Plan by Proctor Matthews Architects

Do not scale from drawing.




Holder Mathias architects
London: 020 7287 0735 www.holdermathias.com


A buffer must be provided at the south of the site in order to protect the privacy of surrounding spaces and allow the preservation of existing, mature trees.




Views through the development must be provided to maintain a connection with the wooded area to the south



An access point to the site should be introduced in order to elevate congestion at the existing site entrance which is a blind turning.






Some relief to the site boundary line must be introduced in order to avoid a dense linear sightline along Tweedy Road.



Overlooking between the new building and the existing listed building should be respected. No oblique views within 15m of the northern most window should be created.

incorporated into the design.

The pocket park to the west of the park should be



No direct overlooking within 21m will be acceptable.